

# CLOSE CALL INCIDENT



#### WHERE?

- CENTRAL AIR STATION, BUILDING 4607
- HIGH PRESSURE COMPRESSOR #4
- BLOWDOWN LINE FOR WATER/OIL CONDENSATE

Mitchell Britt
PM, PP&C Contract





### WHAT HAPPENED?

VALVE BODY BURST DUE TO OVER-PRESSURIZATION

# DRIVING EVENTS

- VALVE INSTALLED DURING CONSTRUCTION
  - INTRODUCED A HAZARD TO OPERATIONS
  - NOT DOCUMENTED ON DESIGN OR "AS-BUILT" DRAWINGS
- HAZARD RECOGNIZED AND SYSTEM "SAFED" BY OPENING VALVES, REMOVING HANDLES, AND TAGGING "DO NOT CLOSE"
- PERMANENT FIX NOT IMPLEMENTED
- CORRECTION TO CONFIGURATION NOT IMPLEMENTED

### LESSONS LEARNED

- FIELD MODIFICATIONS SHOULD BE ANALYZED ACCORDING TO DESIGN REQUIREMENTS AND DOCUMENTED
- WORK ORDER CONTROL SYSTEMS SHOULD BE DESIGNED TO ELIMINATE HUMAN ERROR POTENTIAL

## CORRECTIVE ACTIONS

- ALL VALVES HAVE BEEN REMOVED
- FULLY AUTOMATED SYSTEM IS BEING DEVELOPED TO BETTER CONTROL WORK ORDERS
- PERIODIC REVIEWS OF SAFETY-RELATED WORK ORDERS ARE BEING CONDUCTED